



CD103LFC

Large Casting Dots

50 Pack

Parts Included



Large Foam Dots
(50)

External Prosthetic Components

CD103LFC.revB.01312024



Manufactured by Coyote®

419 N. Curtis Rd., Boise, Idaho 83706 USA

(208) 429-0026 | www.coyote.us





ATTENTION

Easily mark problem areas during the casting process using these adhesive foam dots. In place of pen or pencil marks, these dots are placed on the liner over the top of problem areas, or areas in need of extra relief. The adhesive back will keep them in place during casting and will leave a visible prominence on the mold when poured.

See instructions online.

www.coyote.us/instructions-tools

EN | Instructions for Use
DE | Gebrauchsanweisung
FR | Notice d'utilisation
ES | Instrucciones para el uso
IT | Istruzioni per l'uso
NO | Bruksanvisning
DA | Brugsanvisning
SV | Bruksanvisning
NL | Gebruiksaanwijzing
RU | Инструкция по использованию

JA | 取扱説明書
ZH | 中文说明书
KO | 사용 설명서
FI | Käyttöohjeet
CS | Návod k použití
EL | Οδηγίες Χρήσης
PT | Instruções de Utilização
PL | Instrukcja użytkowania
TR | Kullanım Talimatları

