



# CD103SFC

## Small Casting Dots

200 Pack

Parts Included



Small Foam Dots  
(200)

External Prosthetic Components



CD103SFC.revB.01312024



Manufactured by Coyote®  
419 N. Curtis Rd., Boise, Idaho 83706 USA  
(208) 429-0026 | [www.coyote.us](http://www.coyote.us)





## ATTENTION

Easily mark problem areas during the casting process using these adhesive foam dots. In place of pen or pencil marks, these dots are placed on the liner over the top of problem areas, or areas in need of extra relief. The adhesive back will keep them in place during casting and will leave a visible prominence on the mold when poured.

These Casting dots are also used in the fabrication process of our connector plate. When thermoforming place these casting dots on the end of the connector posts to prevent over sanding when finishing the socket.

**See instructions online.**

[www.coyote.us/instructions-tools](http://www.coyote.us/instructions-tools)

EN | Instructions for Use  
DE | Gebrauchsanweisung  
FR | Notice d'utilisation  
ES | Instrucciones para el uso  
IT | Istruzioni per l'uso  
NO | Bruksanvisning  
DA | Brugsanvisning  
SV | Bruksanvisning  
NL | Gebruiksaanwijzing  
RU | Инструкция по использованию

JA | 取扱説明書  
ZH | 中文说明书  
KO | 사용 설명서  
FI | Käyttöohjeet  
CS | Návod k použití  
EL | Οδηγίες Χρήσης  
PT | Instruções de Utilização  
PL | Instrukcja użytkowania  
TR | Kullanım Talimatları

